

CUSTOMER: Hungarian Gas Storage Plc. (MFGT)
PRODUCTS: RUST GRIP®
MARKET: ENERGY & MINING
COUNTRY: HUNGARY (COURTESY OF NESCHVILL'97 Kft)
DATE: DECEMBER 2021



PROJECT DESCRIPTION

Concrete foundation soles needed repairing and strengthening due to high corrosion of the rebars. The problem beside corrosion is the vibration which the industrial cooling ventilators are causing. These vibrations created cracks and severe damage on the pipe holder concrete foundations.

COATING SOLUTION

Treatment consisted of manually removing loose pieces of concrete. Next step was to apply 2 layers of RUST GRIP® with a roller. Subsequently the foundation pedestal could be restored with a cement mortar to regain its original shape. Finally, the concrete sole was completely encapsulated and protected with 2 layers RUST GRIP®.

RESULTS



BEFORE

AFTER



SUPERIOR PRODUCTS
EUROPE

RUST GRIP[®]

REFERENCE



BEFORE



AFTER



BEFORE



AFTER

Superior Products Europe nv/sa

Kampweg 123 | B-2990 Wuustwezel | Belgium

Phone: +32 3 690 02 40 | Fax: +32 3 690 02 41 | www.specoating.com | info@specoating.com

